





STOCK RETURN ADVICE

TABLE OF CONTENT

1	READ THIS FIRST	1
2	STOCK RETURN ADVICE	1
2.1	SEARCH AND SELECT ITEMS FOR STOCK RETURN TO ML	3
2.2	PRINT STOCK RETURN ADVICE FORM	4

1 READ THIS FIRST

- Select from dropdown list
 - Click on 
 - System will display dropdown list of authorize value
- Select for search help;
 - Click on  to view the list.
 - To select value; double click on the value or select value and click 
- For fields with multiple selections allowed;
 - you can click on  to select multiple value


2 STOCK RETURN ADVICE

In this module, user able to:

- Search and select for item for Stock Return to ML
- Download and print Stock Return Advice form

USER CLICKS ON

- User needs to click on **Stock Return Advice** under **Stock Return** category in tree menu.



- **Stock Return Advice** tab will be open upon it.

RETURN DESTINATION

Plant:

Cost Center:

Project:

Work Order No / Network No:

Reference No:

Reservation No:

GRN No:

Type of Work: Project Work Order Cost Center

SELECTION PARAMETER

Plant: *

Storage Location: *

Material: * To

Equipment Status:

Select	Serial Number	Object number	Material	Description	Plant	Stor. Location	Batch	Equipment Status	Valuation type	Begin guarantee	Warranty end	Warranty Status
<input type="button" value="i"/> The table does not contain any data												


2.1 SEARCH AND SELECT ITEMS FOR STOCK RETURN TO ML

Follow the following steps:

- At Return Destination, user may define value to be print on the Stock Return Advice Form;
 - Plant
 - Cost Center
 - Project
 - Work Order No / Network No
 - Reference No
 - Reservation No
 - GRN No
 - Type of Work: Project/ Work Order/ Cost Center

- At Selection Parameter, select/enter the search parameter for the serial number;
 - Plant
 - Storage Location
 - Material Number
 - Equipment Status

RETURN DESTINATION

Plant: 

Cost Center:

Project:

Work Order No / Network No:


Reference No:


Reservation No:




GRN No:



Type of Work: Project Work Order Cost Center

SELECTION PARAMETER

Plant: * 

Storage Location: * 

Material: *  To  

Equipment Status:  

- Click

SELECTION PARAMETER

Plant: *

Storage Location: *

Material: * To ↕

Equipment Status: ↕

Select	Serial Number	Object number	Material	Description	Plant	Stor. Location	Batch	Equipment Status	Valuation type	Begin guaran
<input type="checkbox"/>	ONU FIBERHOME000019	IE000000300000000150	1000000370	ONU (FiberHome)	V002	BX11	GQ000472	DOA	Goods Stock	
<input type="checkbox"/>	STBTM0000000018	IE000000300000000268	1000000377	SET TOP BOX HUAWEI	V002	BX11	GQ000472	DOA	Goods Stock	26.11.2015
<input type="checkbox"/>	ONUFHTM0000000013	IE000000300000000283	1000000370	ONU (FiberHome)	V002	BX11	ZQ000748	FAULTY	Zero Value Stock	26.11.2015
<input type="checkbox"/>	ADSLTM00000000015	IE000000300000000305	1000000356	MODEM WIRELESS ADSL2 4 PORT	V002	BX11	ZV002BX11	FAULTY	Zero Value Stock	26.11.2015
<input type="checkbox"/>	GGG115	IE000000300000000454	1000000370	ONU (FiberHome)	V002	BX11	GV002BX11	DOA	Goods Stock	03.12.2015
<input type="checkbox"/>	ADSLTM00000000025	IE000000300000000513	1000000356	MODEM WIRELESS ADSL2 4 PORT	V002	BX11	ZV002BX11	FAULTY	Zero Value Stock	03.12.2015
<input type="checkbox"/>	ADSLTM00000000026	IE000000300000000514	1000000356	MODEM WIRELESS ADSL2 4 PORT	V002	BX11	ZQ000748	FAULTY	Zero Value Stock	03.12.2015
<input type="checkbox"/>	ADSLTM00000000027	IE000000300000000515	1000000356	MODEM WIRELESS ADSL2 4 PORT	V002	BX11	ZV002BX11	FAULTY	Zero Value Stock	03.12.2015
<input type="checkbox"/>	ONUFHTM00000000024	IE000000300000000542	1000000370	ONU (FiberHome)	V002	BX11	GV002BX11	DOA	Goods Stock	07.12.2015
<input type="checkbox"/>	ONUFHTM00000000027	IE000000300000000545	1000000370	ONU (FiberHome)	V002	BX11	GQ000472	DOA	Goods Stock	07.12.2015

- Choose/select data to print form

SELECTION PARAMETER

Plant: *

Storage Location: *

Material: * To ↕

Equipment Status: ↕


Select	Serial Number	Object number	Material	Description	Plant	Stor. Location	Batch	Equipment Status	Valuation type	Begin guaran
<input type="checkbox"/>	ONU FIBERHOME000019	IE000000300000000150	1000000370	ONU (FiberHome)	V002	BX11	GQ000472	DOA	Goods Stock	
<input type="checkbox"/>	STBTM0000000018	IE000000300000000268	1000000377	SET TOP BOX HUAWEI	V002	BX11	GQ000472	DOA	Goods Stock	26.11.2015
<input type="checkbox"/>	ONUFHTM0000000013	IE000000300000000283	1000000370	ONU (FiberHome)	V002	BX11	ZQ000748	FAULTY	Zero Value Stock	26.11.2015
<input checked="" type="checkbox"/>	ADSLTM00000000015	IE000000300000000305	1000000356	MODEM WIRELESS ADSL2 4 PORT	V002	BX11	ZV002BX11	FAULTY	Zero Value Stock	26.11.2015
<input checked="" type="checkbox"/>	GGG115	IE000000300000000454	1000000370	ONU (FiberHome)	V002	BX11	GV002BX11	DOA	Goods Stock	03.12.2015
<input checked="" type="checkbox"/>	ADSLTM00000000025	IE000000300000000513	1000000356	MODEM WIRELESS ADSL2 4 PORT	V002	BX11	ZV002BX11	FAULTY	Zero Value Stock	03.12.2015
<input type="checkbox"/>	ADSLTM00000000026	IE000000300000000514	1000000356	MODEM WIRELESS ADSL2 4 PORT	V002	BX11	ZQ000748	FAULTY	Zero Value Stock	03.12.2015
<input checked="" type="checkbox"/>	ADSLTM00000000027	IE000000300000000515	1000000356	MODEM WIRELESS ADSL2 4 PORT	V002	BX11	ZV002BX11	FAULTY	Zero Value Stock	03.12.2015
<input checked="" type="checkbox"/>	ONUFHTM00000000024	IE000000300000000542	1000000370	ONU (FiberHome)	V002	BX11	GV002BX11	DOA	Goods Stock	07.12.2015
<input type="checkbox"/>	ONUFHTM00000000027	IE000000300000000545	1000000370	ONU (FiberHome)	V002	BX11	GQ000472	DOA	Goods Stock	07.12.2015

2.2 PRINT STOCK RETURN ADVICE FORM

Follow the following steps:

- Click on

- A popup window will display.



- You may opt to 'OPEN' or 'SAVE' the document

STOCK RETURN ADVICE FORM

DATE: 27.03.2016

RETURN DESTINATION :

Plant : 102A
 Cost Center :
 Project :
 Work Order No/Network No :
 Reference No :
 Reservation No : 0000000000
 GRN No :
 Type Of Work :

RETURN SOURCE :

Plant : V002
 Storage Location : BX11

SIGNATORY :

<p>1. Return By: (returnee)</p> <p>Signature Name Designature Contact No Date</p>	<p>2. Inspected & Approved By: (SP/Executive & Above/ Technical Manager)</p> <p>Signature Name Designature Contact No Date</p>	<p>3. Received By: (Malaysian Logistics Receiving Officer)</p> <p>Signature Name Designature Contact No Date</p>	<p>4. Verified By: (Malaysian Logistics Receiving Officer)</p> <p>Signature Name Designature Contact No Date</p>
---	--	--	--

RETURN SUMMARY :

Material No	Material Description	Equipment Status	Warranty Status	Quantity	Unit
1000000356	MODEM WIRELESS ADSL2 4 PORT	DOA	WITHIN WARRANTY	1	EA
1000000356	MODEM WIRELESS ADSL2 4 PORT	FAULTY	WITHIN WARRANTY	3	EA
1000000370	ONU (FiberHome)	DOA	WITHIN WARRANTY	8	EA
1000000370	ONU (FiberHome)	FAULTY	OUT OF WARRANTY	3	EA
1000000370	ONU (FiberHome)	FAULTY	WITHIN WARRANTY	1	EA

RETURN DETAILS :

Serial No	Material No	Description	Plant	Storage Loc	Batch	Equi Status	Valuation type	Warranty Start Date	Warranty End Date	Warranty Status
ADSLTM100000000064	100000356	MODEM WIRELESS ADSL2 4 PORT	V002	BX11	ZV002BX11	DOA	ZERO VALUE	22.02.2016	22.02.2018	WITHIN WARRANTY
ADSLTM000000000027	100000356	MODEM WIRELESS ADSL2 4 PORT	V002	BX11	ZV002BX11	FAULTY	ZERO VALUE	03.12.2015	03.12.2017	WITHIN WARRANTY
ADSLTM000000000025	100000356	MODEM WIRELESS ADSL2 4 PORT	V002	BX11	ZV002BX11	FAULTY	ZERO VALUE	03.12.2015	03.12.2017	WITHIN WARRANTY
ADSLTM000000000015	100000356	MODEM WIRELESS ADSL2 4 PORT	V002	BX11	ZV002BX11	FAULTY	ZERO VALUE	26.11.2015	26.11.2017	WITHIN WARRANTY
ONUDOA000000000005	100000370	ONU (FiberHome)	V002	BX11	ZV002BX11	DOA	ZERO VALUE	08.03.2016	08.03.2018	WITHIN WARRANTY
ONUDOA000000000004	100000370	ONU (FiberHome)	V002	BX11	ZV002BX11	DOA	ZERO VALUE	08.03.2016	08.03.2018	WITHIN WARRANTY
ONUDOA000000000003	100000370	ONU (FiberHome)	V002	BX11	ZV002BX11	DOA	ZERO VALUE	08.03.2016	08.03.2018	WITHIN WARRANTY
ONUDOA000000000002	100000370	ONU (FiberHome)	V002	BX11	ZV002BX11	DOA	ZERO VALUE	08.03.2016	08.03.2018	WITHIN WARRANTY
ONUDOA000000000001	100000370	ONU (FiberHome)	V002	BX11	ZV002BX11	DOA	ZERO VALUE	08.03.2016	08.03.2018	WITHIN WARRANTY
ONUFHTM000000000095	100000370	ONU (FiberHome)	V002	BX11	GV002BX11	DOA	GOOD STK	18.02.2016	18.02.2018	WITHIN WARRANTY
ONUFHTM000000000024	100000370	ONU (FiberHome)	V002	BX11	GV002BX11	DOA	GOOD STK	07.12.2015	07.12.2017	WITHIN WARRANTY
GGG115	100000370	ONU (FiberHome)	V002	BX11	GV002BX11	DOA	GOOD STK	03.12.2015	03.12.2017	WITHIN WARRANTY
OFM0000001	100000370	ONU (FiberHome)	V002	BX11	ZV002BX11	FAULTY	ZERO VALUE			OUT OF WARRANTY
ONUFULTY0000001	100000370	ONU (FiberHome)	V002	BX11	ZV002BX11	FAULTY	ZERO VALUE			OUT OF WARRANTY
ONUFOULTY0000001	100000370	ONU (FiberHome)	V002	BX11	ZV002BX11	FAULTY	ZERO VALUE			OUT OF

RETURN DETAILS :

Serial No	Material No	Description	Plant	Storage Loc	Batch	Equi Status	Valuation type	Warranty Start Date	Warranty End Date	Warranty Status
										WARRANTY
ONUFOULTY0000002	100000370	ONU (FiberHome)	V002	BX11	ZV002BX11	FAULTY	ZERO VALUE	04.01.2016	04.01.2018	WITHIN WARRANTY